



91-632 REV 01



NOTE: BARE WIRE IN SPEED/TEMP CABLE IS NOT SOLDERED TO CONNECTOR PIN.