



91-1046 REV 01



NOTES:

1. GREEN AND RED WIRES ARE CUT OFF ON BOTH ENDS.
2. INNER BARE WIRE IS CUT OFF INSIDE THE TRANSDUCER.