

NOTES:

1. INNER BARE WIRES ARE CUT OFF INSIDE THE TRANSDUCER ON THE C334 CABLE.
2. VIOLET AND WHITE WIRES ARE CUT OFF ON BOTH ENDS ON THE C334 CABLE.

